




Iron core loss calculation with QuickField



**Vladimir Podnos,
Director of Marketing and Support,
Tera Analysis Ltd.**











**Alexander Lyubimtsev
Support Engineer
Tera Analysis Ltd.**



QuickField Analysis Options

Magnetic analysis suite	
Magnetic Problems	Magnetostatics
	AC Magnetics
	Transient Magnetic
Electric analysis suite	
Electric Problems	Electrostatics (2D,3D) and DC Conduction
	AC Conduction
	Transient Electric field
Thermostructural analysis suite	
Thermal and mechanical problems	Steady-State Heat transfer
	Transient Heat transfer
	Stress analysis







MultiPhysics

Temperature
Field

Electromagnetic
fields




Losses



Thermal
Stresses


Forces



Magnetic state
import

Stresses &
Deformations









Open object interface





QuickField Analysis Options









Magnetic analysis suite	
Magnetic Problems	Magnetostatics
	AC Magnetics
	Transient Magnetic
Electric analysis suite	
Electric Problems	Electrostatics (2D,3D) and DC Conduction
	AC Conduction
	Transient Electric field
Thermostructural analysis suite	
Thermal and mechanical problems	Steady-State Heat transfer
	Transient Heat transfer
	Stress analysis





QuickField Analysis Options

Magnetic analysis suite	
Magnetic Problems	Magnetostatics
	AC Magnetics
	Transient Magnetic
Electric analysis suite	
Electric Problems	Electrostatics (2D,3D) and DC Conduction
	AC Conduction
	Transient Electric field
Thermostructural analysis suite	
Thermal and mechanical problems	Steady-State Heat transfer
	Transient Heat transfer
	Stress analysis





Magnetic analysis applications

Transformers



Motors and generators




Induction heating









Iron cores in transformers








Iron cores in electric motors and generators





Induction heating of steel parts


Carbon steel alloy crankshaft





Iron core loss factors

- Hysteresis losses



- Eddy current losses



Iron loss calculation models

Steinmetz's equation

$$P = k \cdot f^a \cdot B^c$$

Hysteresis models

Bertotti expression:

$$P = P_{hyst} + P_{eddy} + P_{excess}$$

$$P_{hyst} = k_h \cdot f \cdot B_m^2 - \text{hysteresis}$$

$$P_{eddy} = k_c \cdot f^2 \cdot B_m^2 - \text{eddy current}$$

$$P_{excess} = k_e \cdot (f \cdot B_m)^{3/2} - \text{excess}$$

Other models



Iron core losses in AC Magnetics

Bertotti expression approach

Block Label Properties - core E Arnon7

General Core Loss

Pemeability

Edit B-H Curve ...

Nonlinear

Conductivity

$\sigma =$ (S/m) Depends on Temperature

Temperature: (K)

Field Source

$j_o =$ (A/m²)

$\varphi =$ (deg) **f**

Source Mode

Current Density

Total Current

Conductor's Connection

In Parallel

In Series

Block Label Properties - core E Arnon7

General Core Loss

Core Loss Coefficients (optional):

$P_{\text{core}} = P_{\text{hyst}} + P_{\text{eddy}} + P_{\text{excess}} \quad (\text{W/m}^3)$

$K_h =$ Hysteresis Loss: $P_{\text{hyst}} = K_h \cdot B^2 \cdot f$


$K_c =$ Eddy Curent Loss: $P_{\text{eddy}} = K_c \cdot B^2 \cdot f^2$

$K_e =$ Excess Loss: $P_{\text{ex}} = K_e \cdot (B \cdot f)^{3/2}$



Alternative approaches in AC Magnetics and Transient Magnetics core losses:

Custom integral calculation using ActiveField Application Programming interface





QuickField Difference





Iron core loss calculation with QuickField



Alexander Lyubimtsev
Support Engineer
Tera Analysis Ltd.



Iron core loss calculation with QuickField

1. Loss coefficient calculation
2. No-load mode of transformer.
Iron loss calculation.
3. Iron core losses in transient problem



Loss coefficients

Block Label Properties - core E Arnon7

General Core Loss

Core Loss Coefficients (optional):

$$P_{\text{core}} = P_{\text{hyst}} + P_{\text{eddy}} + P_{\text{excess}} \quad (\text{W/m}^3)$$

$K_h = 202$ Hysteresis Loss: $P_{\text{hyst}} = K_h \cdot B^2 \cdot f$

$K_c = 0.116$ Eddy Current Loss: $P_{\text{eddy}} = K_c \cdot B^2 \cdot f^2$

$K_e = 3.31$ Excess Loss: $P_{\text{ex}} = K_e \cdot (B \cdot f)^{3/2}$

Problem specification:

Material density
 $\rho = 7650 \text{ kg/m}^3$

Task:


Calculate the iron loss coefficients.

Bertotti expression:
$$P_{\text{core}} = k_h \cdot f \cdot B_m^2 + k_c \cdot f^2 \cdot B_m^2 + k_e \cdot (f \cdot B_m)^{3/2}$$

*Core loss data of ArnonTM5 non-grain oriented electrical steel are provided by **Arnold Magnetics**.



No-load mode of transformer



All dimensions are in millimeters

Problem specification:

Core permeability $\mu = 2000$

Frequency $f = 400$ Hz.

Winding 1 (primary):

no-load current 20 mA,

number of turns 400

Core loss coefficients:

$$k_h = 124$$

$$k_c = 0.0621$$

$$k_e = 1.86$$

Task:

Calculate the core losses in the no-load mode of transformer.


Bertotti expression $P_{\text{core}} =$

$$k_h \cdot f \cdot B_m^2 + k_c \cdot f^2 \cdot B_m^2 + k_e \cdot (f \cdot B_m)^{3/2}$$



Custom integral programming interface

QuickField



Field data
in the mesh node

Your program


1	Core Loss Calculation		
2			
3	1. Open simulation results in QuickField and bu		
4	2. Specify core loss coefficients		
5	$P = (K_h \cdot f + K_c \cdot f^2) \cdot B^2 + K_e \cdot (f \cdot B)^{1.5}$		
6	K_h	124	
7	K_c	0,0621	
8	K_e	1,86	
9			
10	Calculate Core Loss		
11			
12			
13	Frequency	400	Hz
14	Flux density	9,10654E-11	T
15	Loss	1,29315E-11	W
16	Total Loss		W

Loss data


$$\text{Custom function: } k_h \cdot f \cdot B_m^2 + k_c \cdot f^2 \cdot B_m^2 + k_e \cdot (f \cdot B_m)^{3/2}$$



Transient excitation mode (sin)



All dimensions are in millimeters



Bertotti expression $P_{\text{core}} =$

$$k_h \cdot f \cdot B_m^2 + k_c \cdot f^2 \cdot B_m^2 + k_e \cdot (f \cdot B_m)^{3/2}$$

Problem specification:

Core permeability $\mu = 2000$

Loss coefficients:

$$k_h = 124$$

$$k_c = 0.0621$$

$$k_e = 1.86$$

Frequency $f = 400$ Hz.

Winding 1 (primary):

no-load current 20 mA,


number of turns 400,

Task:

Calculate the core losses in the transient excitation mode of transformer.



Transient excitation mode




All dimensions are in millimeters

Core loss [W/m³]

$$P_{\text{core}} = \max(k_1 f^{\alpha_1} B^{\beta_1}; k_2 f^{\alpha_2} B^{\beta_2})$$

Problem specification:

Core type: 3C81-E
Core permeability $\mu = 2700$
Frequency $f = 20$ kHz.
Winding 1 (primary):
voltage 40 V,
number of turns 80,



Task:

Calculate core losses in no-load mode